



# Technical Data Sheet

## VA8010

*Environmental Meter  
Temperature and Humidity*



## Application

The meter is a temperature and humidity measuring instrument. It is normally used to measure the humidity and temperature in offices, storerooms, buildings and greenhouses.

## Product Features

Display	4 digits LCD Display
Data Hold	√
Dew point temperature	√
Auto Power Off	About 20min
Power	1.5V Battery (AAA)X3
Size	121x60x30 mm (4.76x2.36x1.18 inch)
Weight	~ 180g (6.34 Ounces)

## Product Specifications

Measurement Parameters	°C, °F, %RH (relative humidity), td (dew point temperature)
Measuring Range	-10~+50°C, +14~+122°F, 0~100%RH
Accuracy	±1.0°C, ±1.8°F, ±3%RH (5~95%RH)
Resolution	0.1°C, 0.1°F, 0.1%RH
Sample Rate	1 time sec

## Accessories Included

Free 1.5V x3 AAA batteries
Free protect cover
Free protective carrying case
Free Wrist / String
User Manual



**Sifam Tinsley Instrumentation Ltd**  
 1 Warner Drive, Springwood Industrial Estate,  
 Braintree, Essex CM7 2YW  
 Contact No. : +44 (0) 1376 335271  
[Email: sales@sifamtinsley.com](mailto:sales@sifamtinsley.com)  
[www.sifamtinsley.co.uk](http://www.sifamtinsley.co.uk)